


## Dual Boom Assembly built before 10-1-02



1. Assembly requires that the shaft be liberally lubricated with silicon grease.
2. When sliding seal assembly on shaft, care must be taken when seal assembly is slipped over ring groove to prevent damaging seals.

## Dual Boom Assembly

